



Total Quality. Assured.

545 E Algonquin Road, Suite H
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667
intertek.com

Published:
Revised:

20-Feb-26

Public Notice ID: 2026-122
Page 1 of 2

Safety Concern with Intertek Certified Product / Souci de sécurité avec le produit certifié Intertek Handheld Garment Steamer or Mighty Lil Steamer, PS-510 and PS-550

Notification Type:	Safety / Sécurité
Certification Type:	ETL Listed - US and Canada

Notification

Intertek notifies consumers, retailers and distributors that we have been made aware of counterfeit Intertek certificates in the marketplace as identified below claiming products are Intertek Certified. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été informés de la contrefaçon de certificats Intertek sur le marché comme indiqué ci-dessous les produits de revendication sont certifiés Intertek.

Company Identification

NVision Electrical Appliance Co., Ltd. & Dongguan ESINO Manufacturing Service Co., Ltd

Product Identification

The recalled products are PurSteam Mighty Lil Steamers and PurSteam Elite Travel Steamers, models PS-510 and PS-550, and these products are labeled and using an cETLus Certification Mark control number 4001123 and 5017077, Recall number: 26-250 see link to CPSC. https://www.cpsc.gov/Recalls/2026/Aterian-Recalls-PurSteam-Elite-Travel-Steamers-and-Mighty-Lil-Steamers-Due-to-Risk-of-Serious-Burn-Injury?utm_campaign=&utm_content=&utm_medium=email&utm_source=govdelivery&utm_term=20260206Product.

Photos on Page 2.

Les produits concernés par le rappel sont les défroisseurs vapeur PurSteam Mighty Lil Steamers et PurSteam Elite Travel Steamers, modèles PS-510 et PS-550. Ces produits portent la marque de certification cETLus (numéros de contrôle : 4001123 et 5017077). Numéro de rappel : 26-250 (voir le lien vers le site de la CPSC : https://www.cpsc.gov/Recalls/2026/Aterian-Recalls-PurSteam-Elite-Travel-Steamers-and-Mighty-Lil-Steamers-Due-to-Risk-of-Serious-Burn-Injury?utm_campaign=&utm_content=&utm_medium=email&utm_source=govdelivery&utm_term=20260206Product).

Photos en page 2.

Hazard Involved

The steamers can expel hot water from the steam nozzle during use, posing a serious burn hazard to consumers.

Ces nettoyeurs vapeur peuvent expulser de l'eau chaude par la buse de vapeur pendant leur utilisation, ce qui représente un grave risque de brûlure pour les consommateurs.

What To Do

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.

Photos and Images / Photos et images

